

Hedrix Acrylic Enamel Spray Paint

SURFACE PREPARATION: Surface should be clean and dry — free of dust, dirt, grease, wax and loose paint. Bare or previously painted metal should be primed with the appropriate primer.

SPRAYING TIPS: Cover floor and furniture where spray might settle. Shake can for at least one minute, listening for rattle or mixing ball. During application, shake intermittently for approximately 10 seconds at 1 to 2 minute intervals. Press valve all the way down. Do not extend finger beyond the valve. Hold container about 6 to 8 inches from surface to be sprayed. Do not cover with continuous spray. Move back and forth, releasing sprayhead after stroke. Overlap each stroke. Apply two thin coats rather than one heavy coat. If paint runs or sags, paint is being applied too heavily, or container is too close to surface. For best results, spray at room temperature 68° to 78°F (20° to 26°C).

CLEAN UP: If spray button becomes clogged, pull off and clean with paint thinner, DO NOT stick pins or wire into can opening. Replace spray button firmly with valve opening pointing away from you. After use, invert can and spray for four seconds to clean valve.

Drying Properties:

Set to touch – 10 - 20 minutes

Tack free – 30 minutes

Dry through – 8 hours